

Message Text

CONFIDENTIAL

PAGE 01 STATE 245484

50

ORIGIN FBO-05

INFO OCT-01 EUR-12 ISO-00 A-01 SY-04 OCE-00 CCO-00 SSO-00

OCL-00 /023 R

DRAFTED BY A/FBO:PWSTANGE:CY

APPROVED BY A/FBO:PRSEREY

SY/T:JBADMAL (SUBS)

EUR/EX:HGEISEL (SUBS)

SOV:FMISCH (SUBS)

OC/S:RDRAPIER

----- 024859

O R 071754Z NOV 74

FM SECSTATE WASHDC

TO AMCONSUL LENINGRAD IMMEDIATE

INFO AMEMBASSY MOSCOW

AMEMBASSY BONN

AMEMBASSY LONDON

AMCONSUL FRANKFURT

C O N F I D E N T I A L STATE 245484

E.O. 11652: GDS

TAGS: ABLD, ACOM, ASEC

SUBJECT: POWER PROBLEMS AND POST COMMUNICATIONS AREA

REF: LENINGRAD 1074 AND 1055

MOSCOW FOR RSO, BONN FOR RCO, LONDON FOR ATO, FRANKFURT
FOR RTC, RSS

1. DIFFICULT ANALYZE PROBLEM BASED INFORMATION SUBMITTED.
RECORDS HERE INCOMPLETE FOR BASIC ELECTRICAL SYSTEM SINCE
DETAILS WERE DEVELOPED BY SOVIETS AND FINAL DRAWINGS
WERE NOT SUBMITTED TO DEPARTMENT FOR REVIEW AND COMMENT.

2. REQUIRE CLARIFICATION FOLLOWING CONSIDERATIONS SOONEST:

(A) UNDERSTAND THE TWO TRANSFORMERS ARE PHYSICALLY LOCATED
CONFIDENTIAL

CONFIDENTIAL

PAGE 02 STATE 245484

OUTSIDE PREMISES WITH FEEDER LINES TO SIX PANELS IN

BUILDING POWER ROOM. CONFIRM EXACT CAPACITY AND NUMBER OF FEEDER LINES FROM EACH TRANSFORMER TO THE SIX PANELS IN POWER ROOM.

(B) CONFIRM WHETHER ONLY ONE THREE-PHASE CIRCUIT FROM PANELS IS INVOLVED CURRENT CRISIS. CONFIRM CAPACITY OF LINE FROM PANEL IN POWER ROOM TO BREAKER SERVICING METER FOR THE ABOVE MENTIONED THREE-PHASE CIRCUIT. IF ADDITIONAL CIRCUITS ALSO ENDANGERED, REPORT FULL DETAILS.

(C) REPORT EXACT AMOUNT WORK WHICH MANDATORY TO BE ACCOMPLISHED BY SOVIETS.

(D) OF REMAINING WORK WHICH COULD BE DONE BY NON-SOVIETS, REPORT WHETHER OR NOT POST SEABEES COULD ACCOMPLISH IF PROVIDED MATERIAL AND GENERAL INSTRUCTIONS.

(E) ADVISE WHETHER ELECTRICAL FAILURES ARE RESULT SHODDY MATERIAL USED BY SOVIETS OR FROM SOVIET DESIGN NOT MEETING OUR REQUIREMENTS AS GIVEN THEM. IF SO SOVIETS SHOULD BE HELD RESPONSIBLE CORRECT PROBLEM THEIR EXPENSE.

3. UPON RECEIPT FOREGOING INFORMATION AND ANALYSES BY DEPARTMENT, POST WILL BE PROMPTLY INSTRUCTED ON CORRECTIVE ACTION. INGERSOLL

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 07 NOV 1974
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: KelleyW0
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1974STATE245484
Document Source: CORE
Document Unique ID: 00
Drafter: PWSTANGE:CY
Enclosure: n/a
Executive Order: GS
Errors: N/A
Film Number: D740320-0761
From: STATE
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1974/newtext/t19741162/aaaacake.tel
Line Count: 86
Locator: TEXT ON-LINE, ON MICROFILM
Office: ORIGIN FBO
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators:
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: LENINGRAD 1074 AND 1055
Review Action: RELEASED, APPROVED
Review Authority: KelleyW0
Review Comment: n/a
Review Content Flags:
Review Date: 09 MAY 2002
Review Event:
Review Exemptions: n/a
Review History: RELEASED <09 MAY 2002 by shawdg>; APPROVED <31 MAR 2003 by KelleyW0>
Review Markings:

Declassified/Released
US Department of State
EO Systematic Review
30 JUN 2005

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: POWER PROBLEMS AND POST COMMUNICATIONS AREA
TAGS: ABLD, ACOM, ASEC
To: LENINGRAD
Type: TE
Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005